

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. _____

Date : _____

It is certified that an inspection team headed by Aman Jain
Sub. Engineer, TMC (Name of Officers
with designation) from _____ (Name of
Department/Office) inspected the PRATIBHASTHALI GYANODYA Vidyaapeeth
Rewari Range Indore (Name & Address of
the School) on _____ and found that the PRATIBHASTHALI
GYANODYA VIDHYAPEETH (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.

The above valid for a period of _____.

उपयंत्री
सीवरेज परियोजना शाखा
(जल यंत्रालय एवं ड्रेनेज विभाग)
नगर पालिक निगम, इन्दौर

Signature with Seal : Aman JainName : Aman JainDesignation : Sub-Engineer

To

Pratibhasthali Gyanodya Vidhyapeeth,
Rewari Range
Indore

(Name & Address of the Institution)

जावक क्र. 443 दि. 31/07/23

कार्यालय अधीक्षण यंत्री
सीवरेज परियोजना शाखा
(जल यंत्रालय एवं ड्रेनेज विभाग)
नगर पालिक निगम, इन्दौर